Copyright © 1999 WSDOT TDO Interchange Viewer: SR 509 - SR 509 11th St Couplet/A Street NOT TO SCALE DO NOT USE THIS DRAWING FOR ANY Not for use for engineering or other purposes requiring dimensional accuracy Collision Coding Notes: Highway Turns COLLISIONS OCCURRING AFTER 2/1/1998 NB veh turn right, code 1AA NB veh straight, code 10C NB veh turn left, code 1AC S Pacific WB veh straight, code 7BB MP 0.20 WB veh turn right, code 70B Begin Couplet -MP 0.27 SR 509 SR 509 SR 509 CO,11THST -MP 0.60 __ 11th St MP 0.22-Collision Coding Notes: MP 0.23-Highway Turns NB veh turn left, code 10C NB veh straight, code 10A SB veh turn right, code 50B MP 0.14 SB veh straight, code 5DB City Waterway WB veh turn right, code 70B 12th St WB veh turn left, code 7BA SB WB veh straight, code 7BB -MP 0.35 Collision Coding Notes: 509 Between these points on couplet පි Code NB veh as "0" MP Direction & 509 "D3" or "D4" impact location Code SB veh as -MP 1.22B=MP 0.00 "B" MP Direction & End Back Equation "D1", "D2" or "D6" impact location End SR 509 CO SR 509 13th St -Collision Coding Notes: Highway Turns MP 0.05 EB veh turn left, code 3AA Collision Coding Notes: NB veh straight, code 1CB **Highway Turns** NB veh turn right, code 1AA Refer to SR 705 Drawing NB veh straight, code 1AC for this ramp SB veh turn left, code 5DC SR 509 SB veh straight, code 5DB Junction SR 509 CO 11THST EB veh straight, code 3DC Historical Alianment Notes: Tacoma, Pierce County EB veh turn right, code 3DB This portion of SR 509 and all of SR 509 CO 11THST were EB veh turn left, code 30C turned back to the City of Tacoma-Eff. 2/1/1998 WSDOT Olympic Region 509 NOT TO SCALE 9/11/2004